

Jacksons Track Community Reference Group

Site Inspection 1 (Date: Friday 26 August 2016)

NOTES /ACTIONS

Site	Location	Existing Conditions	Proposed Improvements - Signs
1	Near No. 1136 (first curve)	<ul style="list-style-type: none"> 3 new poles, 1 new sign 	<ul style="list-style-type: none"> Install 3 CAMs as per standard Tilt signs to reduce glare effect
2	Near Football Oval	<ul style="list-style-type: none"> Existing 80 speed signs near footy oval 	<ul style="list-style-type: none"> Extend 80 speed limit zone to outside of football oval and public gardens area subject to VicRoads approval 60 Speed Limit sign out of Jindivick needs readjustment
3	Near Damaged guard rail	<ul style="list-style-type: none"> 4 new posts 	<ul style="list-style-type: none"> 1st post – remove 2nd post – retain 3rd post – retain 4th post – retain
4	Intersection of Rokeby Jindivick Road	<ul style="list-style-type: none"> Existing CAMs 	<ul style="list-style-type: none"> Existing CAMs Replace exiting GIVE WAY sign 1st post – retain 2nd post – remove 3rd post – retain 4th post – tilted, add westbound CAM 5th post – remove, install guide posts 6th post – remove, install guide posts
5	Outside No. 1225	<ul style="list-style-type: none"> 3 new posts 	<ul style="list-style-type: none"> Remove all posts and don't install any signs Install new warning signs 'DIP' at both ends of dip
6	Right corner near no. 1290 East of Hutchison Road	<ul style="list-style-type: none"> 3 new posts 1 new sign 	<ul style="list-style-type: none"> Remove all signs Install guide posts instead
7	Near 1360	<ul style="list-style-type: none"> 6 new posts and signs 	<ul style="list-style-type: none"> Trim and prune overhanging vegetation 1st post – remove 2nd post – retain 3rd post – retain 4th post – retain 5th post – retain 6th post – retain
8	100m before Jacksons Track (gravel section)	<ul style="list-style-type: none"> 3 new posts and 3 new signs 	<ul style="list-style-type: none"> Retain all signs
9	Near the gravel extension road to Jacksons Track	<ul style="list-style-type: none"> 3 new posts and 3 new signs 	<ul style="list-style-type: none"> 1st post – retain 2nd post – remove 3rd post – retain Review the spacing between all CAMs north of slip lane (gravel Jacksons Track extension)
10	Downhill on Jindivick Neerim South Road	<ul style="list-style-type: none"> Newly installed CAMS 	<ul style="list-style-type: none"> North-west bound downhill Check spacing of CAMs
11	Sweeping curve at the bottom of the valley - Neerim South Jindivick Road	<ul style="list-style-type: none"> Newly installed CAMS 	<ul style="list-style-type: none"> Retain all CAMs Check spacing of CAMs 3 signs may be enough
12	Before Gleeson Road (right turn corner uphill)	<ul style="list-style-type: none"> Newly installed CAMS 	<ul style="list-style-type: none"> 'Concealed Intersection' sign is lost among CAMs, possibly relocate 1st post – retain
13	At Gleeson Road	<ul style="list-style-type: none"> Newly installed CAMS 	<ul style="list-style-type: none"> Remove some of the CAMs where it blocks the road name

			<ul style="list-style-type: none"> • Realign STOP sing to face appropriate direction • Check spacing of CAMs
14	Right bend after Gleeson Road	<ul style="list-style-type: none"> • Newly installed CAMS 	<ul style="list-style-type: none"> • Retain CAMs
15	Right bend before bridge	<ul style="list-style-type: none"> • Newly installed CAMS 	<ul style="list-style-type: none"> • Check spacing of CAMs
16	At bridge / river	<ul style="list-style-type: none"> • Newly installed CAMS 	<ul style="list-style-type: none"> • Remove all 3 posts and signs • Install reflectors on guard rail
17	Bend after bridge	<ul style="list-style-type: none"> • Newly installed CAMS 	<ul style="list-style-type: none"> • Retain CAMs
18	Bend after bridge where speed limit changes from 80 to 100	<ul style="list-style-type: none"> • Newly installed CAMS 	<ul style="list-style-type: none"> • Retain CAMs • Remove CAM that hides the speed limit sign (next to electricity pole) – looking eastbound
19	Existing CAMs behind guard rail located next to steep embankment (on the south)	<ul style="list-style-type: none"> • Newly installed CAMS 	<ul style="list-style-type: none"> • Retain CAMs
20	Right turn bend	<ul style="list-style-type: none"> • Newly installed CAMS • 5 posts with 2 signs 	<ul style="list-style-type: none"> • Remove all signs and posts
21	Near new guard rail (next to No. 325 – the green house gully)	<ul style="list-style-type: none"> • 6 new posts – remove about 3 of them 	<ul style="list-style-type: none"> • Check bracket and bracing of CAMs • 1st post – remove • 2nd – 6th post - retain • Add reflectors on guard rail

S.No.	Location	Proposed Improvements - Road and Drains
1	Jindivick township – Intersection of Main Jindivick Road	<ul style="list-style-type: none"> • Road culverts in front of Jindivick café to be looked at • Road culvert outside church to be looked at •
2	No. 1190	<ul style="list-style-type: none"> • Roadside drains and crossroad culvert clearing
3	Near intersection of Hutchinson Road	<ul style="list-style-type: none"> • Clear cross road culvert • Repair edge breaks
4	Heathermile B& B (near No. 1345)	<ul style="list-style-type: none"> • Pavement repair • Edge break repair • Roadside drain clearing
5	Near Jacksons Track (unsealed section)	<ul style="list-style-type: none"> • Remove Hirschberg sign
6	300m from intersection of gravel unsealed 'Jacksons Track'	<ul style="list-style-type: none"> • Roadside drain clearing • Water flowing across from private driveway (to investigate)
7	At Gleeson Road	<ul style="list-style-type: none"> • Pavement repair • Cross road culvert clearing • Roadside drain clearing
8	200m past Tarago Road	<ul style="list-style-type: none"> • Driveway Culvert • Water flowing across the road from private driveway (to investigate)
9	Neerim South Jindivick Road	<ul style="list-style-type: none"> • Pavement sounds rough (large aggregate sealing material)
10	General on Neerim South Jindivick Road	<ul style="list-style-type: none"> • Roadside drainage and shoulder flanking



Disclaimer Note

While all due skill and attention has been used in presenting this information, the State of Victoria and the Baw Baw Shire Council and their employees shall not be liable in any way for loss of any kind including, damages, costs, interests, loss of profits or special loss or damage arising from any error, inaccuracy, incompleteness or other defect in this information. By receiving this information the recipient acknowledges that the State of Victoria and the Baw Baw Shire Council makes no representations as to the accuracy or completeness of this information and the recipient ought to carry out its own investigations if appropriate.

Copyright © Department of Environment, Land, Water and Planning, Victoria Government and the Baw Baw Shire Council 2016

Site Inspection 1 - Page 1

Prepared By: Haunu Suan

7/09/2016

1:6000
On A3





